


## **FIELD INSPECTION**


Project Name:	Mountain Valley Pipeline	Inspector:	Matthew Grant
Inspection Date:	Tuesday, June 11, 2019	Project Contact:	Brian Clauto
Spread: Roanoke County AR 288 AR 289 Montgomery County MP235 St12453 AR268.1	Spread H	Weather (Wet/Dry/Rain):	Dry
STAGE OF CONSTRUCTION: (Check all that apply)			
☐ Clearing	Rough Grading	Trench Excavation	Pipe Assembly, Testing & Installation
Backfilling and Grade	e Restoration	& Stabilization	Other: Dormant
		Yes No N/A	
Are controls installed and implemented in accordance with the approved $\square$ $\square$ erosion and sediment control plan and stormwater management plans?			
Are all control measures properly maintained in effective operating			
2 condition in accordance with good engineering practices and, where applicable, manufacturer specifications?			
3 Areas of offsite sediment deposition were observed?  □ □			
Comments: Inspected designated streams and wetlands included: W-IJ10,W-KL11, W-Q10, S-Q20, W-26, W-Z7, S-Z16 Wetlands W-IJ10 and W-Q10 have been impacted by road gravel off access AR288.  Recommended Corrective Action: Maintain all controls per the approved plan and specs and remove escaped road gravel.			
	action deadline date applies to all conditions nd/or corrective actions are not completed by the		ee noted. If listed condition(s) currently ons may be issued to the entity responsible for
Inspector Signature: Date: <u>6-24-19</u>			



## FIELD INSPECTION PHOTO LOG

Project Name: <u>Mountain Valley Pipeline</u> Date:Tuesday, June 11, 2019










Fig. 3. Escaped road gravel off AR 288.

